

ASBESTOS CLEARANCE CERTIFICATION

SITE OF CERTIFICATION: 23 Dumaresq Street, Dickson ACT

TIME OF CERTIFICATION: 12:15 PM, 13 October 2021

BACKGROUND:

The residence at 23 Dumaresq Street, Dickson ACT was visually inspected on 13 October 2021 for the presence of asbestos and asbestos-containing materials following asbestos removal works conducted by Crown Independence Pty Ltd on 13 October 2021.

As shown below, the works involved removal of all asbestos cement roof & wall sheeting from the garage prior to its demolition.



CERTIFICATION:

As required under the ACT *Work Health and Safety Regulation 2011*¹ and in accordance with the ACT-approved *How to Safely Remove Asbestos Code of Practice*², visual inspection of the removal area following the removal works showed no evidence of asbestos-containing dust or debris in or around the area.

AUTHORISED ASSESSOR:



DR ANDRE KLEIN
Class A Asbestos Assessor
NSW licence no. LAA001032

¹ ACT *Work Health and Safety Regulation 2011*, section 473, <http://www.legislation.act.gov.au/sl/2011-36/default.asp>, accessed 13 October 2021.

² Safe Work Australia & ACT Government, *How to Safely Remove Asbestos Code of Practice*; <https://www.legislation.act.gov.au/ni/2020-548/>, accessed 13 October 2021.