



**ACT**  
Government

Chief Minister, Treasury and  
Economic Development

Our ref:CM2023/3272

Your ref:

Dr Su Wild-River  
Environment Protection Authority  
Office of the Environment Protection Authority  
GPO Box 158  
Canberra ACT 2601

Dear Dr Su,

**Subject: Detailed Site Investigation, Block 4 Section 109, Amaroo**

Please find enclosed a copy of the detailed site investigation report titled 'Detailed Site Investigation, Block 4 Section 109, Amaroo' for review by the Environment Protection Authority.

The following summarises the investigations undertaken and the outcomes of the report:

- Topsoil was encountered to a depth of approximately 0.4 m across the site;
- Fill material was observed beneath the topsoil at locations Pit 104, Pit 105, Pit 106 and Pit 109 which ranged in thickness from 0.6 m to 2.1 m;
- Natural material was observed beneath the topsoil or fill where it was encountered;
- Water infiltrated five (5) test pits at a depth of approximately 2 m below ground level; and
- Concentrations of COPCs were below the adopted HIL/HSL C and EIL/ESL criteria.

In summary, no indications of contamination that may compromise the suitability of the site for the proposed tennis club were identified.

Should you have any questions regarding this assessment, then please do not hesitate to contact me on 0481 092 985.

Yours sincerely,

Nathan Greig  
Senior Project Manager  
Sport and Recreation  
Level 2, 220 London Circuit  
Canberra City, ACT, 2601

22 June 2023